



## **Release Notes – SD Consoles V1090**

May 2019

### **New Features**

Integrated control of Klang monitoring System (requires KOS 4.0+)

SD12-96 is now available as an upgrade from [www.digico.biz](http://www.digico.biz) SD12-96 has 96 Input channels and 48 output Busses.

SD10 now has 144 inputs into 64 Busses.

SMPTE test loop back has been added to SD7Q Test.

### **Fixes since V1069**

Improved worksurface communications in SD12

Closing a Dynamic EQ panel could cause an Access Violation.

In audio IO, Ports could not be disconnected.

Insert returns on output busses would stop passing audio after on Optocore remap. (SD7Q).

Digital Insert return levels were not recalled correctly on session load (SD7Q).

Stereo channel Gates triggers were only responding to the left side audio level. (SD7Q)

Routing the solo buss internally within the console would not always function correctly. (SD7Q)

---